


PRE-Shipment Inspection Report(PSI)

PRE-SHIPMENT INSPECTION REPORT (PSI)

General Informat	on:
SGR Inspection report:	131216
Client name:	
Product name:	High-heeled sandals(leathers)
Inspection Location:	Dongguan/Guangdong
Inspection Date:	20 th Sep, 2010
Order Number:	805951
Reference number:	RLP763YB908
Order Quantity:	9600pairs
Qty Ready for Inspection (%):	9600pairs (100%)
Supplier/Vendor:	Je
Manufacturer:	Mi
Inspection Type:	PS
Inspector Name: Ste	ven Wang F



Inspection Result Summary Result **Findings/Remarks** CRITICAL MAJOR MINOR Found Beyond 0 11 13 AQL: Visual & Workmanship (Part A) AQL 0 10 10 Max Checked 200 200 200 Conformed Quantity Check (Part B) Conformed Product Specification (Part C) Product measurement&Weight(Part D) Pending Refer to measurement chart. Labeling & Marking (Part E) Conformed Packing and Packaging(Part F) Conformed Tests & Special Requirement (Part G) Conformed Failed **OVERALL INSPECTION RESULT:** (Client has the final decision to Reject or Approve) **Impotant Remarks** No. **Description:** Result 1. Approval sample provided by the factory Conformed Supporting pictures to explain the necessary remarks:

NIL

www.SGRInspection.com

NIL







PRE-Shipment Inspection Report(PSI)

Inspection type	Pre-Shipment Inspection
Inspection standard	ANSI/ASQ Z1.4 - 2003 (Equivalent to ISO 2859-1)
Sampling plan (Single)	Normal
General Inspection Level (Visual / Workmanship)	Level II
Special Inspection Level	S-2
Workmanship: AQL for Critical / Major / Minor	Not Allowed / 2.5 / 2.5
Sampling Size for Critical / Major / Minor	200/ 200 / 200 Pcs
Total number of packages (cartons)	1600ctns
Quantity of cartons available for inspection / No. of cartons	1600ctns/ 40
selected and inspected	
	121,54,167,54,183,218,65,236,92,318,350,362,418,429,
Number on the inequated sectors	437,457,483,523,553,576,591,623,630,654,672,701,714
Number on the inspected cartons	,723,748,759,782,916,917,1083,1120,1189,1235,1287,1
	345, 1567

PO Number	ltem Number	Defective Description	Critical	Major	Mino
805951	RLP763YB908	Damager on counter/strap		3	
		Broken stitches		3	
		Open seam		1	
		Gapping between the upper and the heel		1	
		Sock off		1	
		Wrinkled on back counter		1	
	~	Peel off		1	
		Dirty mark			4
		Glue mark on strap			4
		Over glue			3
		Untrimmed raw edge			1
		Back counter not match in pairs			1
		Total Defects Found	0	11	13
		Max Allowed	0	10	10
	<u> </u>	Sample Size	200	200	20
		AQLResult	E	Beyond AC	l L
		Defect Photos			
Defective D	escription		Critical	Major	Mino
Damager on	counter/strap			3	





PRE-Shipment Inspection Report(PSI)



Defective Description		Critical	Major	Minor
()non coom			1	

www.SGRInspection.com





Page 3 of 35



PRE-Shipment Inspection Report(PSI)

	NIL		
Defective Description	Critical	Major	Minor
Gapping between the upper and the heel		1	
Pefective Description	NIL	Major	Minor
Defective Description	Critical	Major	Minor
Sock off		1	

www.SGRInspection.com





Page 4 of 35



PRE-Shipment Inspection Report(PSI)



www.SGRInspection.com





Page 5 of 35



PRE-Shipment Inspection Report(PSI)



Glue mark on strap

www.SGRInspection.com





Page 6 of 35



PRE-Shipment Inspection Report(PSI)





Defective Description		Critical	Major	Minor
Untrimmed raw edge	×			1

www.SGRInspection.com





Page 7 of 35



PRE-Shipment Inspection Report(PSI)



B.Quality Check

General request: 100% of the total order quantity must be finished and 80% of the total order quantity must be packed before inspection.

-- If the actual packed units are less than 80%, the result must be "Failed"

-- If the actual packed units are more than 80%, the result must be "Passed"

	Order	Shipi Qua		Actual Quanti	•	Units F	inished	Units P	acked	Units Finis		Sample Size
Item No.	Quantity Units	Units	cartons		, in the second	Quantit v	%	Quantit v	%	Quantit	%	0120
/good/balck	4800	4800	800	4800	800	4800	100	4800	100	0	0	100
/Nude/black	4800	4800	800	4800	800	4800	100	4800	100	0	0	100
Total	9600	9600	1600	9600	1600	9600	1600	9600	1600	0	0	200

www.SGRInspection.com


Page 8 of 35







Result: Passed





Page 9 of 35





08 AQ



PRE-Shipment Inspection Report(PSI)



www.SGRInspection.com





Page 10 of 35



PRE-Shipment Inspection Report(PSI)



Products (outside view)



Compare with approved sample (outside view):right one is approval sample



Products (bottom view)



Compare with approved sample (bottom view):right one is approval sample

2.NUDE/BLACK

www.SGRInspection.com





Page 11 of 35

.

:**2008** d



PRE-Shipment Inspection Report(PSI)



Products (front view)



Compare with approved sample (front view):left one is approval sample



Products (back view)



Compare with approved sample (back view):right one is approval sample

www.SGRInspection.com





Page 12 of 35



PRE-Shipment Inspection Report(PSI)





Products (inside view)

Compare with approved sample (inside view):right one is approval sample

www.SGRInspection.com





Page 13 of 35




PRE-Shipment Inspection Report(PSI)



Products (outside view)



Compare with approved sample (outside view):left one is approval sample



Products (bottom view)



Compare with approved sample (bottom view):left one is approval sample







PRE-Shipment Inspection Report(PSI)



D1. Product d	limensions														
Exped	cted Result					Actu	al Find	ding / Q	Comme	ents				Resul	t
Measure pairs/si Approval sample are inconsistent	e,if the measure (all sizes of bul	ement		Pl	ease re	efer to	measu	remen	t chart	below				N.A	
D2. Product v	veight cted Result		1			Act	ual Fi	adina	/ Comn	nonte		1		Resu	1+
	leu Nesun						facility			nenta				N.A	n
	Expecte	Siz	:e3	Siz	ze4	Siz	e5	Siz	ze6	Siz	:e7	Siz	e8	Si	ze
	Approval sample size 4	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right
Insole Length	240mm	233 mm	233 mm		240 mm	247 mm	247 mm	254 mm		260 mm	260 mm	267 mm	267 mm	/	1
Heel Height (if applicable)	120mm	120 mm	120 mm	· · · · · · · · · · · · · · · · · · ·		120 mm	120 mm	123 mm	123 mm	123 mm	123 mm	123 mm	123 mm	1	1
Back Height	54mm	53mm	53mm	54mm	54mm	55mm	55mm	56mm	56mm	58mm	58mm	60mm	60mm	/	/







PRE-Shipment Inspection Report(PSI)



Expe	cted Result					Act	ual Fir	nding /	Comn	nents				Resu	lt
	size, following thre k Length; Ball Girtl	,		P	lease i				nt char		/			N.A	
	Exported	Siz	e3	Siz	e4	Siz	:e5	Siz	.e6	Siz	e7	Siz	:e8	Si	ze
	Expected	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right
Last length	1	233 mm	233 mm	240 mm	240 mm	247 mm	247 mm	254 mm		260 mm	260 mm	267 mm	267 mm	1	1
Ball girth	1	212 mm	212 mm	216 mm	216 mm	220 mm	220 mm	224 mm		229 mm	229 mm	233 mm	233 mm	1	/
						Pictu	ires:								







PRE-Shipment Inspection Report(PSI)



E. Labeling & Marking		
E1. Logo & Specification		
Expected Result	Actual Finding / Comments	Result
Compare the main label with	Same as approval sample ,please refer to picture below	Passed
approved sample		



Products(Logo view) :GOLD/BLACK



Compare with approved sample (logo view):top one is approval sample

www.SGRInspection.com

Page 17 of 35





PRE-Shipment Inspection Report(PSI)



Products(Logo view) :NUDE/BLACK

Compare with approved sample (logo view):top one is approval sample

www.SGRInspection.com






Page 18 of 35



PRE-Shipment Inspection Report(PSI)



Pictures:

www.SGRInspection.com





Page 19 of 35



PRE-Shipment Inspection Report(PSI)



F. Packi	ng and Packag	ing	
F1. Unit pao	-		
Exp	ected Result	Actual Finding / Comments	Result
		1prs/innerbox, with 1pc of anti-mould chip, cardboard and	N.A
		tissue, 2pcs of polybag in each box.	
		Pictures:	







PRE-Shipment Inspection Report(PSI)



www.SGRInspection.com

Page 21 of 35







PRE-Shipment Inspection Report(PSI)

Expected Result		Actual Finding /	Comments	Result
		All shoes filled with	paper.	N.A
		Pictures:		
-3.Outer packing :	All s	hoes filled with paper.		
Expected Result		Actual Finding /	Comments	Result
Refer to the client's SPEC		Same as the client's	SPEC	Passed
	So	lid color solid size:6prs	s per carton	
4. Carton information: Expected Result		Actual Finding	Commente	Result
		All picked cart		Result
		Smell	Dryness	Filling
Report actual finding			-	
Report actual finding		No smell.	🖾 Dry	Yes, correct
Report actual finding		No smell.	Dry Humid	Yes, correct
Report actual finding				
Report actual finding		Strong smell.	Humid	No, too empty
Report actual finding		Strong smell.Irritating smell	Humid	No, too empty No, too full
Report actual finding		Strong smell. Irritating smell Walls	Humid Uet Fastening	No, too empty No, too full Sealing
Report actual finding		Strong smell. Irritating smell Walls 3 ply (1 wall)	Humid Uet Fastening Staples	 No, too empty No, too full Sealing Regular Reinforced Security / printed
Report actual finding		□ Strong smell. □ Irritating smell Walls □ 3 ply (1 wall) □ 5 ply (2 walls)	Humid Humid Uet Fastening Staples Glue	 No, too empty No, too full Sealing Regular Reinforced Security / printed
Report actual finding		□ Strong smell. □ Irritating smell Walls Walls □ 3 ply (1 wall) ☑ 5 ply (2 walls) □ 7 ply (3 walls)	Humid Humid Humid Uet Staples Glue Other	 No, too empty No, too full Sealing Regular Reinforced Security / printed
Report actual finding		□ Strong smell. □ Irritating smell Walls Walls □ 3 ply (1 wall) □ 5 ply (2 walls) □ 7 ply (3 walls) Binding	 Humid Wet Fastening Staples Glue Other Protective sheet 	 No, too empty No, too full Sealing Regular Reinforced Security / printed Safety marking
Report actual finding		□ Strong smell. □ Irritating smell Walls Walls □ 3 ply (1 wall) □ 5 ply (2 walls) □ 7 ply (3 walls) Binding ○ None	 Humid Wet Fastening Staples Glue Other Protective sheet None 	 No, too empty No, too full Sealing Regular Reinforced Security / printed Safety marking Fragile







PRE-Shipment Inspection Report(PSI)







Open view of export carton

5 ply (2 walls)

Expected Result	Actua	I Finding / Comments	Result
	Please refe	er to picture below	N.A
The dimensions of an export car	ton (L x W x H) cm are	Carton number	L x W x H (cm)
close to dimension marked on spe	ec	437 52x31x32	
		723	52x31x32
		782	52x31x32
		18	52x31x32
		318	52x31x32
	Picture	s:	

www.SGRInspection.com





Page 23 of 35



PRE-Shipment Inspection Report(PSI)



www.SGRInspection.com

Page 24 of 35







PRE-Shipment Inspection Report(PSI)

			ICSUNICA #49 #49 12 2 3 前 4 5 6 4 7 8 9 4 9 4 9 4 9 4 9 4 9 4 9 4 9 4 9 4 9 4
Weight of car	tons	Weight of cartons	
7. Carton front mark : Expected Result	Δα	tual Finding / Comments	Resu
Refer to the client's SPEC		SPEC, please refer to picture below	Passed
		ures:	
CTN NO. 330	1 hours	NIL	
Front mar	k		
8. Carton side mark : Expected Result	Act	tual Finding / Comments	Resu
8. Carton side mark : Expected Result Refer to the client's SPEC		tual Finding / Comments SPEC, please refer to picture below	Resu Passed







T

SGR Inspection

PRE-Shipment Inspection Report(PSI)

UNDER NU.: 805951COLOUR: NUDE/ BLACKSIZE: 05 PAIRS: 06 QTY: 6BULKQTY: 6PRSN.W: 3.3KGSG.W: 5.9KGSMEAS:52X31X32CM	ORDER NO.: 805951 COLOUR: GOLD/ BLACK SIZE: 08 PAIRS: 06 OTY: 6 N.W: 45 N.W: 45 KGS G.W: 71 KGS MEAS:52X31X32 CM
Side mark	Side mark

G. On SiteTes	sts and Special Requirements:		
Test item	Test description / requirements	Actual Finding / Comments	Result
Carton drop test-3carton	Carton Drop Test on 3 cartons 10 times (1 corner/3 edges/6 sides)	Checked on 3cartons	Passed
D. B. Hort B. O.			Neli
Color shading check-All samples	Within the same piece: put the same color parts side by side and indentify the different dye lot. 2. Color shading check among all of the inspected pieces: place them side by side as per picture "color shading check attached" and indentify the different dye lotMinimum grey scale 4 is acceptable for color shading in the same piece and minimum grey scale 3/4 is acceptable for color shading among the different pieces.	Checked on all sample size	Passed

www.SGRInspection.com





Page 26 of 35



PRE-Shipment Inspection Report(PSI)



www.SGRInspection.com






Page 27 of 35



PRE-Shipment Inspection Report(PSI)



www.SGRInspection.com





Page 28 of 35



PRE-Shipment Inspection Report(PSI)



www.SGRInspection.com





Page 29 of 35



PRE-Shipment Inspection Report(PSI)



www.SGRInspection.com






Page 30 of 35



PRE-Shipment Inspection Report(PSI)



www.SGRInspection.com

Page 31 of 35





08 AQ



PRE-Shipment Inspection Report(PSI)



www.SGRInspection.com






Page 32 of 35

O 9001:2008 Certified



PRE-Shipment Inspection Report(PSI)



www.SGRInspection.com






Page 33 of 35



PRE-Shipment Inspection Report(PSI)



www.SGRInspection.com

Page 34 of 35





8 AQS

AQSIQ Licence N° 134

icence



PRE-Shipment Inspection Report(PSI)



The above results reflect our findings at time and place of inspection and this report does not relieve sellers / buyer from contractual liabilities, and responsibilities for their products or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring anytime thereafter

******End of the report*****

www.SGRInspection.com





Page 35 of 35