

PRE-Shipment Inspection Report(PSI)

PRE-SHIPMENT INSPECTION REPORT (PSI)

General Informati	ion:	
SGR Inspection report:	140216	
Client name:	Converse Limited	
Product name:	Trousers	
Inspection Location:	ZheJiang	
Inspection Date:	20 th Nov, 2010	
Order Number:	1786	
Reference number:	CWV5994	
Order Quantity:	1200pcs	
Qty Ready for Inspection (%):	1200pcs(100%)	
Supplier/Vendor:	R&L Garment Limited	
Manufacturer:	Zhongyu Garment factory	
Inspection Type:	PSI	
Inspector Name: Mic	chael Tan	Report Approved By: Ben Yang

Inspection Result Summary

	Result		Findings/R	Remarks	
			CRITICAL	MAJOR	MINOR
ACL - Maria & Mariananakin (Dart A)	Within	Found	0	4	6
AQL: Visual & Workmanship (Part A)	AQL	Мах	0	5	7
		Checked	80	80	80
Quantity Check (Part B)	Conformed				
Product Specification (Part C)	Conformed				
Product measurement&Weight(Part D)	Pending	Remark 1			
Labeling & Marking (Part E)	Conformed				
Packing and Packaging(Part F)	Conformed				
Tests & Special Requirement (Part G)	Pending	Remark 2,3	3		
OVERALL INSPECTION RESULT:	Pa	assed			
	(Client has	the final de	cision to Rej	ect or App	rove)

No.	tant Remarks Description:	Result
1.	Found some of measurement points were beyond tolerance, please refer to measurement chart below.	Pending
2.	Found 2 color shade batches in bulk .LOT A ,85% similar with reference sample, LOT B,	Pending

www.SGRInspection.com

Page 1 of 30





3.

SGR Inspection

PRE-Shipment Inspection Report(PSI)

15% darker than reference sample(Grade 4)

The pants will be wrinkled on surface after packaging

Pending

Supporting pictures to explain the necessary remarks:





Found 2 color shade batches in bulk .LOT A ,85% similar with reference sample, LOT B, 15% darker than reference sample(Grade 4)

The pants will be wrinkled on surface after packaging

Inspection Standards	
Inspection type	Pre-Shipment Inspection
Inspection standard	ANSI/ASQ Z1.4 - 2003 (Equivalent to ISO 2859-1)
Sampling plan (Single)	Normal
General Inspection Level (Visual / Workmanship)	Level II
Special Inspection Level	S-2
Workmanship: AQL for Critical / Major / Minor	Not Allowed / 2.5 / 4.0
Sampling Size for Critical / Major / Minor	80/ 80 / 80Pcs
Total number of packages (cartons)	50ctns
Quantity of cartons available for inspection / No. of cartons selected and inspected	50ctns / 8ctns
Number on the inspected cartons	12,23,37,42,48,7,19,25

PO Number	ltem Number	Defective Description	Critical	Major	Minor
1786	CWV5994	Poor stitches(miss stitches) at crotch-MAJ		1	
		Drawn yarn(broken) at back york-MAJ		1	
		Broken stitches-MAJ		1	
		Coarse yam at hem-MAJ		1	
		Untrimmed thread ends-MIN			3

www.SGRInspection.com

Page 2 of 30







PRE-Shipment Inspection Report(PSI)

FRE-31			
Roping/ Puckering -MIN			1
Loose stitches at back pocket-MIN			1
Seam slippage-MIN			1
Total Defects Found	0	4	6
Max Allowed	0	5	7
Sample Size	80	80	80
Result	Pass	Pass	Pass
Defect Photos			
Defective Description	Critical	Major	Minor
Poor stitches(miss stitches) at crotch-MAJ		1	
	NIL		
Defective Description	Critical	Major	Minor
Defective Description Drawn yarn(broken) at back york-MAJ	Critical	Major 1	Minor
	NIL		Minor
			Minor

www.SGRInspection.com







PRE-Shipment Inspection Report(PSI)



www.SGRInspection.com


Page 4 of 30







PRE-Shipment Inspection Report(PSI)




ISO 9001:2008 Certified



PRE-Shipment Inspection Report(PSI)





B.Quality Check

General request: 100% of the total order quantity must be finished and 80% of the total order quantity must be packed before inspection.

- -- If the actual packed units are less than 80%, the result must be "Not Conformed"
- -- If the actual packed units are more than 80%, the result must be "Conformed"

	Order	Ship	ment	Actual	Insp.	Linita E	iniched	Linita D	aakad	Units	Not	Sample
ltom No	Order	Qua	intity	Quant	ity	Units F	inished	Units P	аскец	Finis	hed	Size
Item No.	Quantity Units	Units	cartons	Units	cartons	Quantit y	%	Quantit y	%	Quantit y	%	
CWV5994	1200	1200	50	1200	50	1200	100	1200	100	0	0	80
Total	1200	1200	50	1200	50	1200	100	1200	100	0	0	80
					- Mar							

Result: Passed

C. Product Status&Specification					
. Color / Style	/Material				
Expected	l Result	Actual Finding / Comments	Result		
		Same as approval sample, please refer picture below	Passed		
		Pictures:			

www.SGRInspection.com





Page 6 of 30



PRE-Shipment Inspection Report(PSI)



Front view(bulk products)



Compare with approved sample (front view):right one is approval sample



Front 1/2 top view(bulk products)



Compare with approved sample (1/2 front top view):right one is approval sample

www.SGRInspection.com





Page 7 of 30



PRE-Shipment Inspection Report(PSI)



Front 1/2 bottom view(bulk products)



Back view(bulk products)



Compare with approved sample (1/2 front bottom view):right one is approval sample



Compare with approved sample (back view):right one is approval sample

www.SGRInspection.com





Page 8 of 30



PRE-Shipment Inspection Report(PSI)



www.SGRInspection.com



ISO 9001:2008 Certified



PRE-Shipment Inspection Report(PSI)



Compare with approved sample (detail review): right one is approval sample



Compare with approved sample (detail review): right one is approval sample



Compare with approved sample (detail review): right one is approval sample



Similar to PANTONE 19-4010TPX

01. Product dimensions				
Expected Result	Actual Finding / Comments			
Refer to SPEC	Found some of measurement points were beyond	Pending		
	tolerance, please refer to measurement chart below.			
2. Product weight				
Expected Result	Actual Finding / Comments	Result		
	No facility for check	N.A		

www.SGRInspection.com





Page 10 of 30



PRE-Shipment Inspection Report(PSI)

1		~		i		1		-		-	-	-			i	i
measurement point	6			8			10			12			14			TOL
waistband height	4.5	1	1	4.5	1	1	4.5	-0.5	-0.2	4.5	1	1	4.5	1	1	0.3
waist-along top to edge	32.5	-1.5	0.3	33.7	-0.5	0.3	36.1	0.4	-0.5	37.3	0.8	0.3	38.5	-0.5	0.3	1
high hip-8.4cm below waistband straight	37	-1	-0.5	38.2	0.5	1	40.6	-1.4	0.5	41.8	-0.9	1	43	0.5	1	1
front rise-form top of fr.wb to crotch seam	22.5	1	0.5	23	1	0.5	24	-0.5	1	24.5	1	0.5	25	1	0.5	0.5
back rise-form top of bk.wb to crotch seam	37.5	-0.5	-0.5	38	-0.9	0.3	39	-1	-0.5	39.5	-1	0.3	40	-0.9	0.3	0.5
thigh-below crotch seam	23	-0.3	-0.6	23.6	-0.5	1	24.8	-0.6	-0.5	25.4	-0.7	1	26	-0.5	1	0.6
knee-33cm below crotch	15	-0.5	-0.2	15.5	1	1	16.5	1	1	17	-0.5	1	17.5	1	1	0.5
hem opening-straight	12.5	-0.5	1	13	0.3	1	14	1	0.3	14.5	-0.2	1	15	0.3	1	0.5
inseam regular	81	1	-1.3	81	0.5	-0.5	81	-1	0.5	81	1	0.5	81	0.5	1.1	1
front pocket width-at bottom wb seam	8.5	0.2	1	9.1	1	1	9.1	1	1	9.7	1	1	9.7	1	1	0.3
front pocket height-at below wb at sideseam	5	1	-0.2	5	1	1	5	0.2	1	5	1	1	5	1	1	0.3
front pocket bag length	18.5	1	1	18.5	0.2	1	18.5	1	-0.2	18.5	1	1	18.5	1	1	0.3
coin pocket width-top	6	0.1	1	6.6	1	-0.2	6.6	1	1	7.2	0.2	1	7.2	0.2	1	0.3
coin pocket length-at center	7	1	-0.2	7	1	1	7	0.1	1	7	1	-0.2	7	1	-0.2	0.3
coin pocket position- form bottom for wb	1.5	1	1	1.5	0.1	1	1.5	1	-0.2	1.5	1	1	1.5	1	1	0.3
coin pocket position- from side seam	1.5	1	1	1.5	1	-0.2	1.5	1	1	1.5	0.1	1	1.5	0.1	1	0.3
fly length-under wb	7.4	1	1	8.4	1	1	9.4	0.2	1	9.4	1	-0.2	10.4	1	-0.2	0.3
back yoke height-at center back	3.5	0.2	1	3.5	0.2	1	3.5	1	-0.2	3.5	1	1	3.5	1	1	0.3
back yoke height-at side seam	5.5	1	-0.2	5.5	1	-0.2	5.5	1	1	5.5	1	1	5.5	1	/	0.3

Pictures:



waist-along top to edge



high hip-8.4cm below waistband straight

www.SGRInspection.com





Page 11 of 30



PRE-Shipment Inspection Report(PSI)



www.SGRInspection.com


Page 12 of 30







PRE-Shipment Inspection Report(PSI)



www.SGRInspection.com

Page 13 of 30





ice



PRE-Shipment Inspection Report(PSI)



Expected Result	Actual Finding / Comments	Result
Check the retail price stated	Same as the client's SPEC	

www.SGRInspection.com

Page 14 of 30





AQS

AQSIQ Licence N° 134

cence



on hangtag was conformed to that stated on client's P/O.

Leather patch sewn on right back of waistband

PRE-Shipment Inspection Report(PSI) Passed

Hang tag attached at left front belt **Pictures:** Hangtag(front view) Hangtag(back view) Leather patch view Flasher view

F 1. U	nit packing : Expected Result	Actual Finding / Comments	Result
		Each piece in fold packed into an individual poly bag sealed by	Passed
		self-adhesive tape.	
		Pictures:	







Page 15 of 30



PRE-Shipment Inspection Report(PSI)









PRE-Shipment Inspection Report(PSI) CONVERSE THER Y. Polybag printed Each piece in fold packed into an individual poly bag Fold view Fold view Fold view Fold view

www.SGRInspection.com

Page 17 of 30







PRE-Shipment Inspection Report(PSI)

2. Inner packing : Expected Result	Actual Finding / Comments	Result
	6 piece packed into an bigger poly bag	Passed
	Pictures:	
3.Outer packing : Expected Result	Actual Finding / Comments	Result
	6pcs solid color asserted size per big poly bag per carton and	Passed
	24pcs solid color solid size per carton	
	Size: 6 8 10 12 14	
	Pre-pack :1 :: 2 :: 2 :: 1 :: 1	
	Pls see pictures	
	Pictures:	
	<image/> <image/>	
4. Carton information:		
	Actual Finding / Comments	Result
4. Carton information:	Actual Finding / Comments Please refer to picture below Smell Dryness	Result Passed Filling





PRE-Shipment Inspection Report(PSI)

No smell.	🖾 Dry	Yes, correct
Strong smell.	🗌 Humid	No, too empty
Irritating smell	🗌 Wet	No, too full
Walls	Fastening	Sealing
3 ply (1 wall)	Staples	🛛 Regular
5 ply (2 walls)	🖾 Glue	Reinforced
7 ply (3 walls)	🗌 Other	Security /
Binding	Protective sheet	Safety marking
🛛 None	None	Fragile
Nylon bands	🖂 Тор	Keep upright
Metal bands	Bottom	Other
		~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~

## **Pictures:**



F5. Dimensions of export cartons :

www.SGRInspection.com





Page 19 of 30



#### PRE-Shipment Inspection Report(PSI)

Actual Finding / Comments	
Please refer to picture below	
Carton number	L x W x H (cm)
12	58x40x25
23	58x40x25
37	58x40x25
42	58x40x25
48	58x40x25
	refer to picture below Carton number 12 23 37 42





Dimensions of export cartons (Lenght)



NIL

Dimensions of export cartons (Width)

Dimensions of export cartons (Hight) F6. Weight of cartons: (on 5 cartons) : **Actual Finding / Comments** Result **Expected Result** Please refer to picture below - without any reference data Pending from the buyer (1kg=2.2Lbs/1lb = 0.45kg) Carton number Weight (kg)

www.SGRInspection.com

Page 20 of 30







12       11.5         23       11.6         37       11.7         42       11.59         48       11.81         Pictures:			PRE-Shipmer	nt Inspection Report(PSI)
37       11.7         42       11.59         48       11.81         Pictures:         NIL         NIL         NIL         NIL         T. Carton front mark :         Expected Result         - without any reference data from the buyer       Please refer to picture below       Pending         8. Carton side mark :         Expected Result       Actual Finding / Comments       Result         * without any reference data from the buyer       Please refer to picture below       Pending			12	11.5
42       11.59         48       11.81         Pictures:         NIL         NIL         NIL         T. Carton front mark :         Expected Result         Actual Finding / Comments         Result         ***********************************			23	11.6
48     11.81       Pictures:       NIL       NIL       NIL       To Carton front mark :       Expected Result       Actual Finding / Comments       Result       • without any reference data from the buyer       Please refer to picture below       Please refer to picture below       Pending       ***********************************			37	11.7
Pictures:         Image: Second			42	11.59
77. Carton front mark :       NIL         Expected Result       Actual Finding / Comments       Result         * without any reference data from the buyer       Please refer to picture below       Pending         78. Carton side mark :       Expected Result       Actual Finding / Comments       Result         * without any reference data from the buyer       Please refer to picture below       Pending         * Without any reference data from the buyer       Please refer to picture below       Pending			48	11.81
7. Carton front mark :       Actual Finding / Comments       Result         • without any reference data from the buyer       Please refer to picture below       Pending         • 8. Carton side mark :       Actual Finding / Comments       Result         • without any reference data from the buyer       Please refer to picture below       Pending         • without any reference data from the buyer       Please refer to picture below       Pending		Pictures		
Expected ResultActual Finding / CommentsResult- without any reference data from the buyerPlease refer to picture belowPending*8. Carton side mark : Expected ResultActual Finding / CommentsResult- without any reference data from the buyerPlease refer to picture belowPending	THE ME AND THE		N	IL
Expected ResultActual Finding / CommentsResult- without any reference data from the buyerPlease refer to picture belowPending*8. Carton side mark : Expected ResultActual Finding / CommentsResult- without any reference data from the buyerPlease refer to picture belowPending				
from the buyerActual Finding / CommentsExpected ResultActual Finding / Comments- without any reference data from the buyerPlease refer to picture below		Actual F	inding / Comments	Result
Expected Result       Actual Finding / Comments       Result         - without any reference data from the buyer       Please refer to picture below       Pending	- without any reference data	Please refer to picture below		Pending
Expected ResultActual Finding / CommentsResult- without any reference data from the buyerPlease refer to picture belowPending				
from the buyer		Actual Finding / Comments Result		Result
		Please refer to picture below Pending		
		Pictures	•	

www.SGRInspection.com





Page 21 of 30



#### PRE-Shipment Inspection Report(PSI)

		PRE-Snipment Inspection Repo	
and the second second second second	IN BLUE AD: 24PZS	TALLA: (° COLOR:BLUE CANTIDAD: 24 PZS G.W: (1 & KGS N.W: (°) KGS MEAST:58X40X25CM MADE IN CHINA	
	Front mark	Side mark	
G. On SiteTe Test item	sts and Special Requirements Test description / requirements		Deput
Carton Drop	Carton Drop Test on 3 cartons 10 times	Actual Finding / Comments Checked on 3 cartons	Result Passed
Test-3carton	(1 corner/3 edges/6 sides)		luooou
Color shading check-All samples	Within the same piece: put the same color parts side by side and indentify the different dye lot. 2. Color shading check among all of the inspected pieces: place them side by side as per picture "color shading check attached" and indentify the different dye lotMinimum grey scale	Found 2 color shade batches in bulk .LOT A ,85% similar with reference sample, LOT B, 15% darker than reference sample(Grade 4)	Passed

www.SGRInspection.com





Page 22 of 30



PRE-Shipment Inspection Report(PSI)



www.SGRInspection.com

Page 23 of 30







#### PRE-Shipment Inspection Report(PSI)

Fitting Test– S2	Product should get fitting correctly and easily, and stable/functional after	No model or dummy was provided by	N.A
	building.	factory for test	
Rub test/color fastness test for fabric – S2	Use a white cloth to rub on product 10cycles, no color transferred should be found	Checked on 8pcs	Passed
		NIL	
Rub test for printing or marking -S2	The resistance of the marking by trying to remove it by rubbing lightly for 15 s within a white piece of fabric soaked with petroleum spirit/ if the it's not available, use the 95% alcohol.	Checked on 8pcs	Passed
		entre de la constant	5
Symmetry comparison Test – All samples	Check if the left and right boat is symmetry at shape, color, size, ect.	Checked on all sample size	Passed

www.SGRInspection.com





Page 24 of 30



#### PRE-Shipment Inspection Report(PSI)



www.SGRInspection.com






Page 25 of 30



#### PRE-Shipment Inspection Report(PSI)



www.SGRInspection.com





Page 26 of 30



#### PRE-Shipment Inspection Report(PSI)

		7453069291934+ 7453069261579+ 7453069231451+ 7453069251543+ 7453069271869- 7453069291778- 7453069261579	50
Burn test: Check once only	Perform the burn test on all the garments made from 100% cotton.	No applicable	N.A
Stretch test for elastic and knitted fabric - S2	- Stretch the garment on the waistband and on the side seam to check the elasticity of the garment - no spandex fibers or stitches brake	Checked on 8pcs	Passed
pocket check - S2	Pocket must be wide enough to accommodate the full hand the pockets position should be balanced	Checked on 8pcs	Passed

www.SGRInspection.com

SO 9001:2008 Certified



Page 27 of 30



#### PRE-Shipment Inspection Report(PSI)



www.SGRInspection.com





Page 28 of 30



H. Additional Pictures	
H1. Other Pictures	
NIL	NIL
Semi-finished Products	Under packing Products
H2. Other Information and pictures	
<image/> <image/> <section-header><section-header><section-header><section-header><section-header></section-header></section-header></section-header></section-header></section-header>	<text></text>
Original signature of Factory Manager accepting SGR Inspection conditions	Original Signature of factory manager on the draft report acknowledging SGRInspection inspector findings



Page 29 of 30







#### PRE-Shipment Inspection Report(PSI)

The above results reflect our findings at time and place of inspection and this report does not relieve sellers / buyer from contractual liabilities, and responsibilities for their products or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring anytime thereafter

******End of the report******

www.SGRInspection.com





Page 30 of 30